

Safety Report for Sandon Parish Council Meeting

For 14th November 2018 PC meeting

Agenda Item 9

INSPECTIONS

Roe Green

The Safety Officer continues to undertake monthly inspections of Roe Green play equipment and sports fields, the latest of which was conducted on 10th November 2018. The inspections included a drive/walk through the Village to cover general observations of any PC assets or Village amenities that may require attention or represent a hazard.

The status on the 3 items identified for maintenance in the 18th June 2018 RoSPA inspection of Roe Green is as follows:-

- Soccer Goal Posts: Continued deterioration and rusting noted.

Action: The Chair of the Sports Club requested that that these are retained for informal village use and he agreed to organise re-painting in accordance with the RoSPA inspection report.

*Status: **Painting not yet done – Safety Officer to chase.***

- Toddler 8ft Swing: Cradle seat to be replaced.

*Action: **Completed.***

- Surfacing beneath play equipment: The honeycomb rubber safety surfacing has sunk into the ground.

*Action: The SO has raised a query with the supplier for their recommended action, they have requested photographs which have now been taken and Safety Officer is **awaiting the supplier's response.***

The grass on the cricket field and green is being kept well mown.

General: The discarded old and broken chairs behind the cricket pavilion remain. 16 items of litter collected, and 2 sections of carpeting under the benches noted on 10th November.

The Calor-Gas cylinder has been removed from the Pavilion veranda.

Roads – Numerous pot-holes in local roads have been filled, but rapidly reappear. The North end of Gannock Road is particularly bad.

Latest inspection check sheet No143 with full details is available from SO - M Wicksteed.